

SS-222



RoadSafe Truck Sales  
Truck Detail Sheet

Basic Vehicle Info

Year	2019
Make	International
Model	MV
Engine (Size & Type)	6.7 ISB Cummins
Transmission	Auto / Allison
Drivetrain (2WD/4WD)	2wd
Mileage	117,360
VIN	1HTEUMML7KH441735

Body / Configuration

Body Type (Pickup, Flatbed, etc.)	Flatbed
Bed/Body Notes (Length, Toolboxes, etc.)	16' Steel Floor Blue Ridge Bed
Exterior Color	White
Interior Color	Black / Gray

Condition Snapshot

Overall Condition	<u>Excellent</u> Good   Fair   Needs Work
Tire Condition	New <u>Good</u> Fair   Poor
Notable Damage / Rust	One small cut in drivers side floor next
Recent Service / Repairs	serviced @ Ascendance / Dot in house

Key Selling Points

- 250 HP Cummins Engine
- Very Clean, Interior 10/10
- Mash rated SS180 M, Brand new Solar Tech Message Board

Photo Check

Exterior	<input checked="" type="checkbox"/>
Interior	<input checked="" type="checkbox"/>
Odometer	<input checked="" type="checkbox"/>
Vin Tag	<input checked="" type="checkbox"/>

For any questions, please contact,

Name \_\_\_\_\_  
Number \_\_\_\_\_